

Dot Weld Offroad Cleaning Recommendations

- Rinse all dirt, mud, etc away
- Use plenty of Mild Soap and Water
- Never wipe or rub windshield with dust, dirt, mud, etc. on it
- Never use any cleaners that contain Amonia
- You may use Novus Plastic Polis, Plexus, or any equivalent product for cleaning, polish, removing swirl marks or fine scratches
- These can be found at most ATV / UTV dealers