

# NOZZLE CHART

## PSI

GPM	500	1000	1500	2000	2500	3000	3500	4000	4500	5000	6000
2.0	5.5	4.0	3.5	3.0	2.5	2.5	2.0	2.0	2.0	2.0	1.5
2.5	7.0	5.0	4.0	3.5	3.0	3.0	2.5	2.5	2.5	2.0	2.0
3.0	8.5	6.0	5.0	4.0	4.0	3.5	3.0	3.0	3.0	2.5	2.5
3.5	10.0	7.0	5.5	5.0	4.5	4.0	3.5	3.5	3.5	3.0	3.0
4.0	12.0	8.0	6.5	5.5	5.0	4.5	4.5	4.0	4.0	3.5	3.5
4.5	13.0	9.0	7.5	6.5	5.5	5.0	5.0	4.5	4.0	4.0	4.0
5.0	15.0	10.0	8.0	7.0	6.5	6.0	5.5	5.0	4.5	4.5	4.0
5.5	20.0	11.0	9.0	8.0	7.0	6.5	6.0	5.5	5.0	5.0	4.5
6.0	20.0	12.0	10.0	8.5	7.5	7.0	6.5	6.0	5.5	5.5	5.0
6.5	20.0	13.0	11.0	9.0	8.0	7.5	7.0	6.5	6.0	6.0	5.5
7.0	20.0	15.0	15.0	10.0	9.0	8.0	7.5	7.0	6.5	6.5	5.5
7.5	30.0	15.0	12.0	11.0	10.0	8.5	8.0	7.5	7.0	6.5	6.0
8.0	30.0	20.0	13.0	12.0	10.0	9.0	8.5	8.0	7.5	7.0	6.5
8.5	30.0	20.0	15.0	12.0	11.0	10.0	9.0	8.5	8.0	7.5	7.0
9.0	30.0	20.0	15.0	13.0	12.0	11.0	10.0	9.0	8.5	8.0	7.5
10.0	30.0	20.0	20.0	15.0	13.0	12.0	11.0	10.0	10.0	9.0	8.0
12.0	40.0	30.0	20.0	20.0	15.0	15.0	13.0	12.0	12.0	11.0	10.0
15.0	42.5	30.0	30.0	30.0	20.0	20.0	20.0	15.0	15.0	15.0	12.0