

# BONDERITE C-IC 33 AERO

## ACIDIC CLEANER

(KNOWN AS TURCO ALUMIPREP 33)

---

### INTRODUCTION:

BONDERITE C-IC 33 AERO (known as TURCO ALUMIPREP 33) is a non-flammable phosphoric acid based cleaner, brightener and prepaint conditioner for aluminum. BONDERITE C-IC 33 AERO should not be used on high copper bearing aluminum alloys or aluminum castings. Cleaning with BONDERITE C-IC 33 AERO produces a chemically clean and corrosion free aluminum surface.

BONDERITE C-IC 33 AERO can be used to deep clean and brighten an aluminum surface prior to welding, painting or to prepare the surface for a subsequent conversion coating. BONDERITE M-CR 1201 AERO (known as ALODINE 1201) (opaque) and BONDERITE M-CR 1001 AERO (known as ALODINE 1001) (invisible) coating chemicals produce the best affordable substrate for both paint adhesion and corrosion resistance.

### OPERATING SUMMARY:

**Brush Application:**

For light oxidation and corrosion removal dilute one part BONDERITE C-IC 33 AERO with five parts water.

For heavy oxidation and corrosion removal dilute one part BONDERITE C-IC 33 AERO with two parts water.

**Immersion Application:**

For each 100 parts of bath, add 25 parts of BONDERITE C-IC 33 AERO to 75 parts of water.

**Spray Application using 62-G Applicator:**

Set dilution control on 3 allowing a mix of one part BONDERITE C-IC 33 AERO to three parts water.

### PROCESS:

The usual process to clean and condition aluminum surfaces consists of the following steps:

1. Apply the BONDERITE C-IC 33 AERO solution
2. Water rinse
3. Dry



# BONDERITE C-IC 33 AERO

## ACIDIC CLEANER

(KNOWN AS TURCO ALUMIPREP 33)

---

The usual process to prepare the aluminum surfaces for a chemical coating consists of the following steps:

1. Apply the BONDERITE C-IC 33 AERO solution
2. Water rinse
3. Apply an BONDERITE coating solution
4. Water rinse
5. Dry

### MATERIALS:

1. BONDERITE C-IC 33 AERO
2. BONDERITE M-CR 1201 (known as ALODINE 1201) (optional)
3. BONDERITE M-CR 1001 (known as ALODINE 1001) (optional)

### EQUIPMENT RECOMMENDATION:

Acid resisting (rubber, stainless steel or plastic) buckets, troughs or other suitable container should be used to hold the diluted BONDERITE C-IC 33 AERO solution. Ordinary steel pails may be used, but only for a short time. Galvanized containers should not be used. If production conditions warrant, troughs may be installed to collect the BONDERITE C-IC 33 AERO coating chemical run-off for reuse.

Long-handled, window type brushes, clean cloths or synthetic sponges may be used to brush on the BONDERITE solution.

### APPLY THE BONDERITE C-IC 33 AERO SOLUTION:

#### **Buildup:**

For brush application for light oxidation and corrosion removal, dilute one part BONDERITE C-IC 33 AERO with five parts water.

For brush application for heavy oxidation and corrosion removal, dilute one part BONDERITE C-IC 33 AERO with two parts water.

For immersion application, add 25 parts of BONDERITE C-IC 33 AERO to 75 parts of water for each 100 parts of bath.

For spray application using 62-g applicator, set dilution control on 3 allowing a mix of one part BONDERITE C-IC 33 AERO to three parts water.

**NOTE:** Operators should be equipped with rubber gloves, aprons and goggles to avoid contact with the solution. Adequate ventilation should be provided.

# **BONDERITE C-IC 33 AERO**

## **ACIDIC CLEANER**

**(KNOWN AS TURCO ALUMIPREP 33)**

---

**Operation:**

Selecting the size area to be treated at one time will depend on the method of application, condition of the metal surface, temperature and part configuration. A typical treatment time is where the BONDERITE C-IC 33 AERO solution is in contact with the metal surface between two and five minutes.

BONDERITE C-IC 33 AERO solution is normally applied at temperatures between room and 120° Fahrenheit. If drying does occur, rewet the surface with BONDERITE C-IC 33 AERO solution, prior to water rinsing.

BONDERITE C-IC 33 AERO solution should not be allowed to dry on the metal surface or permitted to reoxidize prior to a thorough rinse. A thorough rinse with clean water is necessary to remove both residual BONDERITE C-IC 33 AERO solution and oils that have been lifted from the metal surface.

Good results start with cleaning. A clean surface is a "water break-free surface". The rinse water sheets out over the aluminum surface, while oil remaining on the surface will cause the water to bead up. Chemical cleaners will lift and break down oils on the surface and assist in rinsing them from the surface on the metal.

BONDERITE C-IC 33 AERO cleaning and conditioning chemicals aggressively attack aluminum oxidation and corrosion to completely remove them, leaving a bright clean metal surface. In the case of heavy corrosion, its removal can be aided by the use of scrubbing. Often a scotch-brite pad is used for scrubbing.

Thorough rinsing after treatment is necessary to remove the residual salts and soils. Their removal will not contaminate a coating chemical or leave a surface condition that will again have a high potential for corrosion.

To avoid streaks and patterns, work from bottom to top.

**STORAGE REQUIREMENTS:**

BONDERITE C-IC 33 AERO will freeze at 15° Fahrenheit. Freezing is not detrimental to the product. It is recommended that the product be kept from freezing. However, should the product freeze, simply thaw it in a warm place and stir it prior to use.

**DISPOSAL INFORMATION:**

Applicable regulations concerning disposal and discharge of chemicals should be consulted and followed.

Disposal information for the chemical products used in this process is given on the Henkel Material Safety Data Sheet for each product.



# BONDERITE C-IC 33 AERO

## ACIDIC CLEANER

(KNOWN AS TURCO ALUMIPREP 33)

---

**PRECAUTIONARY INFORMATION:**

Before handling the chemical products used in the process, the first aid and handling recommendations on the Henkel Material Safety Data Sheet for the product should be read, understood and followed.

The processing bath is acidic. Do not get in eyes, on skin or on clothing. In case of contact, follow the recommendations found in the Material Safety Data Sheet for BONDERITE C-IC 33 AERO.

Before using this product refer to container label and HENKEL SURFACE TECHNOLOGIES MATERIAL SAFETY DATA SHEET for additional precautionary, handling and first aid information.

**NOTICE:**

**The above information and recommendations concerning this product are based upon our laboratory tests and field use experience with this or similar products. However, since conditions of actual use are beyond our control, any recommendations or suggestions are made without warranty, express or implied. Manufacturer's and seller's sole obligation shall be to replace that portion of the product shown to be defective. Neither shall be liable for any loss, damage, or injury, direct or consequential, arising out of the use of this product.**

Rev. 8/2013

---

Henkel Corporation | 32100 Stephenson Highway | Madison Heights, MI 48071  
PHONE: (248) 583-9300 | FAX: (248) 583-2976 | [www.henkelna.com/](http://www.henkelna.com/)

**Trademark usage**

Except as otherwise noted, all trademarks in this document are trademarks of Henkel Corporation in the U.S. and elsewhere. ® denotes a trademark registered in the U.S. Patent and Trademark Office.

The data contained herein are furnished for information only and are believed to be reliable. We cannot assume responsibility for the results obtained by others over whose methods we have no control. It is the user's responsibility to determine suitability for the user's purpose of any production methods mentioned herein and to adopt such precautions as may be advisable for the protection of property and of persons against any hazards that may be involved in the handling and use thereof. In light of the foregoing, **Henkel Corporation specifically disclaims all warranties expressed or implied, including warranties of merchantability or fitness for a particular purpose, arising from sale or use of Henkel Corporation's products. Henkel Corporation specifically disclaims any liability for consequential or incidental damages of any kind, including lost profits.**

The discussion herein of various processes or compositions is not to be interpreted as representation that they are free from domination of patents owned by others or as a license under any Henkel Corporation patents that may cover such processes or compositions. We recommend that each prospective user test his proposed application before repetitive use, using this data as a guide. This product may be covered by one or more United States or foreign patents or patent applications.

