

Standard Drill Sizes - Inches

<i>Drill Size</i>	<i>Decimal Equiv.</i>	<i>Drill Size</i>	<i>Decimal Equiv.</i>	<i>Drill Size</i>	<i>Decimal Equiv.</i>	<i>Drill Size</i>	<i>Decimal Equiv.</i>
80 = .0135		43 = .089		8 = .199		25/64 = .3906	
79 = .0145		42 = .0935		7 = .201		X = .397	
1/64 = .0156		3/32 = .0938		13/64 = .2031		Y = .404	
78 = .016		41 = .096		6 = .204		13/32 = .4063	
77 = .018		40 = .098		5 = .2055		Z = .413	
76 = .020		39 = .0995		4 = .209		27/64 = .4219	
75 = .021		38 = .1015		3 = .213		7/16 = .4375	
74 = .0225		37 = .104		7/32 = .2188		29/64 = .4531	
73 = .024		36 = .1065		2 = .221		15/32 = .4688	
72 = .025		7/64 = .1094		1 = .228		31/64 = .4844	
71 = .026		35 = .110		A = .234		1/2 = .500	
70 = .028		34 = .111		15/64 = .2344		33/64 = .5156	
69 = .0292		33 = .113		B = .238		17/32 = .5313	
68 = .031		32 = .116		C = .242		35/64 = .5469	
1/32 = .0313		31 = .120		D = .246		9/16 = .5625	
67 = .032		1/8 = .1250		1/4 (E) = .250		37/64 = .5781	
66 = .033		30 = .1285		F = .257		19/32 = .5938	
65 = .035		29 = .136		G = .261		39/64 = .6094	
64 = .036		28 = .1405		17/64 = .2656		5/8 = .625	
63 = .037		9/64 = .1406		H = .266		41/64 = .6406	
62 = .038		27 = .144		I = .272		21/32 = .6563	
61 = .039		26 = .147		J = .277		43/64 = .6719	
60 = .040		25 = .1495		K = .281		11/16 = .6875	
59 = .041		24 = .152		9/32 = .2813		45/64 = .7031	
58 = .042		23 = .154		L = .290		23/32 = .7188	
57 = .043		5/32 = .1563		M = .295		47/64 = .7344	
56 = .0465		22 = .157		19/64 = .2969		3/4 = .750	
3/64 = .0469		21 = .159		N = .302		49/64 = .7656	
55 = .052		20 = .161		5/16 = .3125		25/32 = .7813	
54 = .055		19 = .166		O = .316		51/64 = .7969	
53 = .0595		18 = .1695		P = .323		13/16 = .8125	
1/16 = .0625		11/64 = .1719		21/64 = .3281		53/64 = .8281	
52 = .0635		17 = .173		Q = .332		27/32 = .8438	
51 = .067		16 = .177		R = .339		55/64 = .8594	
50 = .070		15 = .180		11/32 = .3438		7/8 = .875	
49 = .073		14 = .182		S = .348		57/64 = .8906	
48 = .076		13 = .185		T = .358		29/32 = .9063	
5/64 = .0781		3/16 = .1875		23/64 = .3594		59/64 = .9219	
47 = .0785		12 = .189		U = .368		15/16 = .9375	
46 = .081		11 = .191		3/8 = .375		61/64 = .9531	
45 = .082		10 = .1935		V = .377		31/32 = .9688	
44 = .086		9 = .196		W = .386		63/64 = .9844	