


CUSTOMER'S THREADING CHART
 FOR
 401, 403, 404, 500, 503 Machines



No Longer used in threading
 Bypass this part

- 1
- 2
- 3

It is also recommended to use 66class plastic bobbins now. Some metal bobbins have a exposed ring in the center where pressed together, that ring may cause jamming in the bobbin case area. Smooth metal bobbins should be ok

Return this chart with machine.

Form 21643 (1273)

This was supplied when a Knit Kit was installed in The above mentioned models. Not sure if those made in Germany had the same kit offered or not. The kit consisted of an improved hook & modifying the bobbin case thread pull off block