


GUN DOG SUPPLY

Summit Trex Dog Boots

Sizing Chart



NOTE: It is important to select “Actual Size” under the print size options when printing this PDF file.

Sizes available: 1.5", 1.75", 2.0", 2.25", 2.5", 2.75", 3.0", 3.25"

Measure across the widest part of paw when bearing weight.

1. Have your dog stand on a firm surface.
2. Print this chart and place under front paw.
3. Lift dog's opposite front paw, so that weight is placed firmly only the paw being measured.
4. Measure that distance and choose correct boot size from the figures above.

If you are between sizes, choose the smaller size.