


To program the Symbol LI4278 for communication to a USB host, follow the steps below.

1. **REPLACE BATTERY INSIDE THE SCANNER WITH THE NEW ONE THAT'S INCLUDED IN THE BOX.**
2. Connect the USB interface cable to the cradle and to your host (PC)
3. If using an external power supply (to allow fast charging of the scanner), insert the power cable into the power port on the back of the cradle, and connect the power supply to an AC power outlet
4. Let the scanner fully charge. Takes about 3 hours if using an external power supply and about 5 hours using the USB cable
5. Scan "Set All Defaults" barcode below



RETURN TO FACTORY DEFAULTS

6. Scan the barcode (S/N) located on the cradle



7. Scan "HID Keyboard Emulation" barcode below



HID KEYBOARD EMULATION

8. Scan "Cradle Host" barcode below



CRADLE HOST

9. Scan the following barcodes below in order to "add an Enter key after each scan"

1



SCAN OPTIONS

2



<DATA><SUFFIX 1>

3



ENTER