


Lake in the Hills Airport

3CK



Pilots:
Do NOT cross the "Hold Lines"
unless ready for
immediate departure AND
runway/approach clear of traffic



MAGNETIC DECLINATION is
2° 23' West on 07/01/2003, using
NDGC Geomag Version 4.0
Annual Change: 6 Minutes West/Year