



1968 Shelby Lower Valance

Two cutouts are required before final prep and paint for the clearance of the bumper brackets.

Test fit with brackets installed and mark cutout locations accordingly.

Before



After

