


## 1968 Shelby Lower Valance

Two cutouts are required before final prep and paint for the clearance of the bumper brackets.

Test fit with brackets installed and mark cutout locations accordingly.

### Before



### After

